

**Diesel line operating at 900 psi; Exxon, Caribbean off coast of Belize, 2008**

Dent damage due to anchor drag;

Surface hand prepared, dent filled with high compressive strength epoxy filler to re-contour pipe and repaired with Aquawrap system.

